

OUT56439

multi

P 131444Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5208.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 23 WAS USED IN MISSION 8036 FLOWN ON 11 AUGUST 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERICS.

B. 9R SIDE: SEVERE EMULSION BLISTERS AND A REPAIRED FILM TEAR ARE IN FRAME 2032. A MANUFACTURING SPLICE EXISTS IN FRAME 1137.

C. 9L SIDE: TRANSVERSE PLUS DENSITY STREAKS 0.1" WIDE ARE IN FRAMES 0001, 0002, AND 2061. TWO ROWS OF MINUS DENSITY DOTS SPACED 1.7" APART ARE LOCATED 2.6" AND 3.3" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT THE FIRST 60 FRAMES. A HEAT SPLICE IS BETWEEN FRAMES 313 AND 314.

D. BOTH SIDES: PRESSURE ROLLER STATIC AND EDGE STATIC EXIST ALONG BOTH INBOARD AND OUTBOARD SIDES OF THE FILM THROUGHOUT THE MISSION.

13 AUG 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Declassification Review by NGA/DoD

-2-

E. THE CAMERA SHUTTER FAILED TO CLOSE PROPERLY RESULTING IN GROSS OVEREXPOSURE OF 15 FRAMES. IN EACH INSTANCE THE FILM WAS TRANSPORTED WITH THE SHUTTER OPEN WHICH CAUSED 1/3 TO 1/2 OF THE ADJACENT 15 FRAMES TO ALSO BE OVEREXPOSED. THERE WERE NO MAJOR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING OF THE POSITIVE WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 35 PERCENT OF THE MISSION.

GP-1.

S E C R E T

-END OF MESSAGE-